25

CENTRAL INTELLIGENCE AGENCY

COUNTRY Philippines	INFORMATION	REPORT	REPORT NO.	<b>(1A</b> 25X1		
SUBJECT Port Information, Tac	loban					
PLACE ACQUIRED (BY SOURCE)						
DATE ACQUIRED (BY SOURCE)	];					
DATE (OF INFO.)			DATE DISTR. / 3			
OF THE UNITED STATES. WITH AND 794. OF THE U.S. CODE.	ORNATION AFFECTING THE NATIONAL DEFENS IN THE MEANING OF TITLE 18. SECTIONS 79 AS AMENDED. ITS TRANSMISSION OR REVE		NO. OF PAGES 2 25X1C			
PROHIBITED BY LAW. THE REP	OR RECEIPT BY AN UNAUTHORIZED PERSON I REQUESTION OF THIS REPORT IS PROHISITED ALUATED INFORMATION		SUPP. TO REPORT NO.	25X1X		
				25X1A		
. [						

## Approach

- 1. Tacloban is a Customs Port of Entry situated on the west shore at the head of San Pedro Bay, and is 11°15.2' N 124°59.8' E. (Coast and Geodetic Charts 4420, 4423, and 4464 are recommended for use.) As of 20 Sept 54, the following were controlling factors in entering and clearing this port:
  - a. 18' is the maximum allowable draft for vessels entering or leaving this port.
  - b. As the entrance channel buoys are not lighted, the vessel must arrive in time to make the complete bar transit in daylight hours.
  - c. 565' off and at right angles from the end of the berth at Tacloban is a 16' shoal. This shoal makes up to this depth in such a manner as to allow only 460' of safe maneuvering space off the end of the dock. The whole bay is shoal and encumbered with islets, reefs, shoals, and fish traps. Exceptional caution, therefore, should be used in entering and proceeding to the pilot station.

#### Anchorage

2. If bound for Tacloban pier or Anibong pier, vessels should anchor off Egbert Shoal and await pilot. If not bound for the piers, good anchorage will be found in the vicinity of Dio Islet in five or six fathoms, mud bottom. The anchorage is well protected, excepting from the South, and the piers are well protected on all sides. The dredged channel from Dio Islet to Tacloban is constantly silting, and the channel is very narrow.

## Wharf

3.	The	wharf	at	Tacloban	is	a	government-owned,	concrete	structure,	1500	reet	Tong

ONI review(s) completed.

CONFIDENTIAL

D106586

This report is for the use within the USA of the Intelligence components of the Departments or Agencies indicated above. It is not to be transmitted overseas without the concurrence of the originating office through the Assistant Director of the Office of Collection and Dissemination, CIA.

25X1<sup>-</sup>

- 2 -

and 50 feet wide. However, it is liable to silt badly if not kept dredged. The Anibong Point pier is wooden and privately owned. It is in such bad condition that vessels no longer use it.

### Export Items

4. Copra and hemp are the principal items of export.

#### Warehouses

- 5. Numerous warehouses, owned by the shippers, are situated within a short radius of the Tacloban Wharf, with capacities as follows:
  - a. Columbian Rope Company, 800, 1000, and 1200 ton capacity;
  - b. Cia Gral de Tabacos, 650 and 1500 ton capacity;
  - Pacific Copra Export Company, 850 and 1500 ton capacity;
  - d. International Trading Corporation, 650 and 1400 ton capacity;
  - e. Procter and Gamble Trading Company, 3800 ton capacity.

# Labor

6. Labor is supplied locally, and the rate of loading averages 14 tons copra per gang hour. Copra sometimes is loaded from ship's side and lighters are obtained from other sources, as required.

- end -

756.548 \$ 756.543 \$ 756.549 \$ 756.545 \$

confi <b>de</b> ntial/	

25X1